



2024

COMPLETE SOLUTION  
GENUINE QUALITY

---

**Central Slave Cylinder, clutch**



AP

Poor Quality

## 6 difference compared AP and poor quality part

1. diameter. AP part same as genuine dimension.

2. Appearance. AP part same as genuine design.

3. AP part use KOYO bearing.

4. AP part use NSK bearing.

5. wire enamel quality difference. AP use imported one.

6. Design difference. AP is same as genuine design.



**1. Dimeter difference.**

**2. Appearance difference.**

AP: 60mm

Appearance different.

Poor Quality: 55mm



**3.AP bearing**

**4.Poor Quality bearing**

AP bearing is NSK & KOYO

Poor Quality is unknown brand.



5. wire enamel

6.Rotor design

AP used imported wire  
enamel

Poor Quality is domestic  
wire enamel

**ANPU AUTO PARTS CO., LTD**

**E-mail:** sales01@anpuautopart.com

**Address:** Jiujing road 1501, Jiuting, Songjiang, Shanghai, China

**Tel:** 021-57655701

**Cell:** 18221291483