



2024

COMPLETE SOLUTION
GENUINE QUALITY

Air Intake Hose





Appearance:

1. The plastic material is the same PPS.
2. The length from other suppliers differs from the original dimensions.



AP



Other



Poor

High-Temperature Test Results:

1. AP: Burned completely, remains normal.
2. Other: Burned completely, outer layer damaged.
3. Poor: Burned completely, with a rupture.

AP




Tensile Test Results:

- 1.AP:** After breaking, the fabric remains normal.
- 2.Other:** After breaking, the fabric gets tangled together.
- 3.Poor:** Breaks with minimal pull, but the fabric remains normal after breaking.

Other



Poor



ANPU AUTO PARTS CO., LTD

E-mail: sales01@anpuautopart.com

Address: Jiujing road 1501, Jiuting, Songjiang, Shanghai, China

Tel: 021-57655701

Cell: 18221291483